

0007

PRICE RIVER COAL COMPANY

P.O. BOX 629 HELPER, UTAH 84526 (801) 472-3411

To: Jim Your Copy -

File #10
ACT/007/004

Copy to Tom T.
Lynn, Pam

November 15, 1982

CERTIFIED MAIL NO. 3968249
Return Receipt Requested

JIM

NOV 19 1982

Mr. Ronald W. Daniels
Deputy Director
Utah Department of Natural Resources
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Dear Sir:

Price River Coal Company hereby requests permission to delete subsidence monitoring under UMC 784.20 for the following reasons:

1. There are no structures within the area of subsidence.
2. No renewable resources will be materially damaged.
3. No second mining will take place within an approved angle of draw (currently 45° as approved by the U.S.G.S. under the 211 Mining and Reclamation Plan) near sensitive areas. This would prevent subsidence from damaging any sensitive structures such as water tanks, highways, rivers, or railroads. No pipelines are located within the area of subsidence.
4. Due to the extremely mountainous topography, the monitoring results have little, if any, practical value.
5. Data collected to date should be sufficient (3 years monitoring data).

If you have any questions, we would be happy to discuss them with you.

Very truly yours,

K. B. Hutchinson
K. B. Hutchinson
Chief Engineer

RECEIVED
NOV 16 1982

KBH:ga

- cc: Gordon Cook, PRCC
R. L. Wiley, PRCC
L. Adair, PRCC
A. Muse, PRCC
B. McKean, MMS, SLC

**DIVISION OF
OIL, GAS & MINING**

