

November 4, 1982

Memo to Coal File

#7
RE: Price River Coal Company
Price River Coal Complex
ACT/007/004
Carbon County, Utah

The purpose of this memo is to document a phone conversation between myself and Mr. Rob Wiley of Price River Coal Company (PRCC), on the morning of November 2, 1982. The intent of the telephone call was to find out the status of remedial actions required for NOV N82-4-12-2 and NAOC 82-4-9-3.

Mr. Wiley informed me that the remedial actions required for NOV N82-4-12-2, #1 of 2, had been completed. He also reminded me that during the October 13, 1982 portion of the complete inspection that we had observed a backhoe working on the problem associated with the #4 mine drainage system.

Mr. Wiley said that the remedial actions required for abatement of NOV N82-4-12-2, #2 of 2, concerning the disturbed area runoff diversion from the #1 shaft to the sediment pond at Crandall Canyon, was no longer applicable because of the fact there was no more muck water being discharged from the #1 shaft because the #1 shaft had been completed. Also, Lowdermilk had started to excavate the bank where the diversion had been located, initiating the construction of the hilfiker wall in this area.

NAOC's 82-4-9-3, #1 of 3 and #2 of 3, have been completed. The major portion of #2 of 3 had been completed and observed by the inspectors on October 13, 1982. According to Mr. Wiley, the plans which were supposed to have been submitted in accordance with NAOC 82-4-9-3, #3 of 3 on October 27, 1982 were still being worked on and that they would be submitted within one week.

DAVID LOF
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM
Rob Wiley, PRCC