

December 12, 1983


Inspection Memo  
to Coal File:

RE: Price River Coal Company  
Price River Coal Complex  
ACT/007/004, Folder No. 7  
Carbon County, Utah

On May 17, 1983 an inspection was conducted by Division Inspector David Lof at the above mentioned mine site. The purpose of the inspection was to follow up on the abatement of Notice of Violation N82-4-14-1.

The violation pertained to sediment controls at the Castlegate Preparation Plant. The remedial actions required that plans be submitted to the Division adequately addressing sediment control structures, the plans were to be implemented immediately upon Division approval. The operator received approval on the plans in a letter from the Division dated March 10, 1983, and hand delivered to the operator on the same date. The plans involved the construction and maintenance of a number of undisturbed, and disturbed area runoff diversions, construction of a new Sediment Pond # 012 and the reconstruction of an existing impoundment converting it to new Sedimentation Pond #011. At the time of inspection all of the construction had been completed with the exception of bypassing the undisturbed drainage watershed located above the guard shack past old Sediment Pond 012. The operator still needs to seed all the new diversions, berms and sediment pond embankments this fall. A Termination of Notice was served on August 8, 1983 with an effective termination date of May 17, 1983.

At the time of the inspection, the new truck turnaround located at the guard shack had not been constructed.

  
DAVID LOF  
FIELD SPECIALIST

DL:re

cc: Jodie Merriman, OSM  
Joe Helfrich, DOGM

Statistics: Deer Creek Mine Memo dated July 18, 1983