

0029

File ACT/007/004  
#3

**PRICE RIVER COAL COMPANY**

P.O. BOX 629 HELPER, UTAH 84526 (801) 472-3411

June 5, 1985

**RECEIVED**

**JUN 10 1985**

**DIVISION OF OIL  
GAS & MINING**

CERTIFIED RECEIPT REQUESTED  
Certified No. P656 177 308

Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Attn: Ms. Susan Linner

Gentlemen:

As you are probably aware, due to circumstances beyond our control (government intervention, etc.) PRCC has temporarily suspended mining operations.

The Crandall Canyon leach field had not been completed when the suspension was put into effect. Top soil had been dozed into a windrow on one side of the construction site, for resoiling when the field had been constructed.

At this time, we do not know when funds will be available to complete the project. We therefore request permission to leave the topsoil where it is now located rather than hauling it back and forth, etc. The pile will be seeded, bermed and properly maintained until it is restored to its former position over the leach field.

Very truly yours,

PRICE RIVER COAL COMPANY



Kenneth B. Hutchinson  
Chief Engineer

KBH: jp  
cc: G. Cook

