



0019

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

File

October 1, 1986

EXPRESS MAIL RECEIPT REQUESTED  
B 58659732

Mr. Richard Allison  
Project Engineer  
Castle Gate Coal Company  
P. O. Box 449  
Helper, Utah 85426

Dear Mr. Allison:

RE: Notice of Violation N86-4-13-2, Castle Gate Coal Company, Price River Mine Complex, ACT/007/004, Folder #7, Carbon County, Utah

Please find enclosed the above mentioned document which was discussed with you during our September 30, 1986 telephone conversation. As you were told during the conversation the abatement deadline for the violations is October 10, 1986. The time set for abatement of either of the violations may be extended only if the failure to meet the initial deadline is not due to a lack of diligence (UMC 843.12 (c)). Request for abatement deadline extensions must be made through the issuing inspector prior to the deadline.

Please call me as soon as you abate the violations so that you may be considered for Good Faith points, and the violations can be properly terminated.

Sincerely,

David Lof  
Mining Field Specialist

dl

Enclosures

cc: Donna Griffin, OSM  
Ken May, DOGM  
Lowell Braxton, DOGM  
Joe Helfrich, DOGM  
Sue Linner, DOGM

0348Q-60



NO. N 86-4-13-2

notice of violation

To the following Permittee or Operator:

Name CASTLE GATE COAL COMPANY

Mine PRICE  Surface  Underground  Other

County CARBON State UTAH Telephone \_\_\_\_\_

Mailing Address P.O. Box 419 HELPER, UT 84526

State Permit No. ACT/007/004

Ownership Category  State  Federal  Fee  Mixed

Date of inspection SEPT. 26 19 86

Time of inspection 7:30  a.m.  p.m. to 12:15  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is  is not  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling SEPT. 30, 1986

Time of service/mailling 4:20  a.m.  p.m.

RICHARD H. ALLISON, JR.  
Permittee/Operator representative

PROTECT SUPERVISOR  
Title

ISSUED FROM THE DIVISION OFFICE  
Signature

DAVID LOF  
Division of Oil, Gas & Mining representative

MINING FIELD SPECIALIST  
Title

DAVID LOF  
Signature

#4  
Identification Number

SEE REVERSE SIDE  
WHITE-DOG M. YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

~~417~~ 417



NOTICE OF VIOLATION NO. N86-4-13-2

Violation No. 1 of 2

Nature of violation

FAILURE TO CONDUCT SURFACE COAL MINING ACTIVITIES IN ACCORDANCE WITH AN APPROVED PERMIT

FAILURE TO MAINTAIN SEDIMENT CONTROLS

Provisions of act, regulations or permit violated

UMC 771.19

UMC 817.45

Portion of operation to which notice applies

CASTLEGATE PREP PLANT DIVERSION D-4, CULVERT C-4 AND THE REFUSE HAUL ROAD

Remedial action required (including any interim steps)

- 1) RECONSTRUCT D-4 TO MEET DESIGN SPECIFICATIONS
- 2) MAINTAIN THE INLET OF C-4
- 3) REGRADE THE REFUSE HAUL ROAD TO PROVIDE PROPER ROAD DRAINAGE AND ENSURE THAT ALL ROAD RUNOFF IS DIVERTED TO THE APPROPRIATE SEDIMENT CONTROL STRUCTURES

Abatement time (including interim steps)

OCTOBER 10, 1986



NOTICE OF VIOLATION NO. N 86-4-13-2

Violation No. 2 of 2

Nature of violation

FAILURE TO MAINTAIN SEDIMENT PONDS TO PREVENT SHORT CIRCUITING TO THE EXTENT POSSIBLE

Provisions of act, regulations or permit violated

UMC 817.16 (2)

Portion of operation to which notice applies

SEDIMENT PONDS OIL AND OIL-B

Remedial action required (including any interim steps)

REPAIR LEAKS IN THE POND'S SPILLWAY SYSTEM TO PREVENT SHORT CIRCUITING AND ENSURE THAT EFFLUENT LIMITATIONS ARE MET.

Abatement time (including interim steps)

OCTOBER 10, 1986