

0005



**CASTLE
GATE**
COAL COMPANY

Mine File
S. Senior
Price Office

X07/007/004
RECEIVED
AUG 20 1987
DIVISION OF OIL
& MINING

August 18, 1987

Mr. Lowell Braxton
Administrator
Division of Oil, Gas & Mining
3 Triad Center
Suite 350
Salt Lake City, Utah 84180-1203

Dear Mr. Braxton:

Pursuant to UMC 843.20, I am requesting a compliance conference for the purpose of establishing whether permit boundary markers are adequate for compliance with UMC 817.11.

The present boundary marking system was set up by Price River Coal Company and has been adequate to pass complete inspections by both DOGM and OSM. However, recent inspections by OSM on other coal properties have led me to believe that previous standards of marking may not be adequate.

Please respond to this request as soon as possible.

Sincerely,

Richard H. Allison, Jr.
Richard H. Allison, Jr., D.E.
Project Supervisor

RHA:jcr

Sue: Please have the assigned inspector contact Allison and acknowledge receipt of this by DOGM. I'd like the inspector to comment verbally to Allison vis-a-vis his appraisal of present boundary markers as late as the next inspection. Thank you
LH 8/21

cc5.rha817A