

0043

Mine File
S. Linnear



**CASTLE
GATE**
COAL COMPANY

RECEIVED
JAN 23 1987

ACT/007/004

DIVISION OF
OIL, GAS & MINING

January 20, 1987


Mr. Lowell Braxton
Division of Oil, Gas & Mining
Three Triad Center, Suite 350
Salt Lake City, UT 84180-1205

Dear Mr. Braxton:

Pursuant to UMC 817.49(h) Reporting Requirements for MSHA Sediment
Impoundments, I am submitting the following information:

Structure Name:	Schoolhouse Canyon Sediment Pond
MSHA I.D. No.	1221-UT-9-01517-02
Owner:	Castle Gate Coal Company
Address:	P. O. Box 449 Helper, UT 84526

The above named pond has been inspected by myself and I have found no change in geometry from existing plans. This pond was dry most of the year and never discharged through the primary spillway during the previous 12 months. No appreciable accumulation of sediment has occurred in the pond; therefore, the structure still maintains its design capacity. No modifications to the structure have occurred within the past twelve months.



Sincerely,

Richard H. Allison, Jr.
Richard H. Allison, Jr., P.E.
Project Supervisor

RHA:sk

cc: David Miller
MSHA File
Chrono

RHA/027