



NO. N 87-18-1-1

notice of violation

To the following Permittee or Operator:

Name Price River Coal Company (AEP)

Mine LPS Price River Complex (Willow Creek) Surface Underground Other

County Carbon State Utah Telephone (614) 687-1440

Mailing Address P.O. Box 700 Lancaster, Ohio 43130

State Permit No. JNA/007/008 ~~(88/100/100)~~

Ownership Category State Federal Fee Mixed

Date of inspection 8-6-87, 19____

Time of inspection 09:30 a.m. p.m. to 4:30 a.m. p.m.

Operator Name (other than Permittee) Blackhawk Mining Company

Mailing Address C/O Mel Conrad P.O. Box 358 Elmo, UT 84521

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Cert. mailed 8-7-87 Time of service/ mailing 3:00 a.m. p.m.

001 720 854
Permittee/Operator representative

Title

Signature

David W. Darby
Division of Oil, Gas & Mining representative

Geologist - Insp. #18
Title

David W. Darby
Signature

18
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 87-18-1-1

Violation No. 1 of 1

Nature of violation

Failure to construct culverts to avoid plugging and erosion at inlet and outlet.

Provisions of act, regulations or permit violated

UMC 817.163(1)(ii)

Portion of operation to which notice applies

Lower 24" culvert on class II haul road.

Remedial action required (including any interim steps)

Provide erosion protection at inlet and outlet of culvert and remove debris from culvert.

Abatement time (including interim steps)

By September 27, 1987 at 5:00 pm.