

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

February 12, 2009

TO: Internal File

THRU: James D. Smith, Permit Supervisor *JDS 12/12/09*

FROM: April A. Abate, Environmental Scientist II *AAA 2-12-09*

RE: 2008 Fourth Quarter Water Monitoring, Castle Gate Holding Company, Castle Gate Mine, C/007/0004-WQ08-4, Task ID #3165

The Castle Gate Mine is inactive, mostly reclaimed, and is awaiting appropriate conditions to apply for Phase II Bond Release.

Pertinent water monitoring requirement information is in the MRP in Sections 7.5-1 and 7.5-3, and table 7-16.

1. Was data submitted for all of the MRP required sites? YES NO

Springs –

The Permittee is not required to monitor any springs at the Castle Gate Mine.

Streams –

The Permittee is required to sample four intermittent/ephemeral streams (B-11, B-12, B-28, B-45) for flow, and the laboratory parameters outlined in Table 7-16 each quarter.

The Permittee monitored all streams as required during this quarter on December 24, 2008; none were flowing.

Wells–

The Permittee is not required to monitor any wells at the Castle Gate Mine.

UPDES–

There are no active UPDES sites at the Castle Gate Mine.

2. Were all required parameters reported for each site? YES NO

There was no flow at any of the four stream sites.

3. **Were any irregularities found in the data?** YES NO

There was no flow at any of the four stream sites.

4. **On what date does the MRP require a five-year re-sampling of baseline water data.**

The MRP does not require a five-year re-sampling of baseline water data.

5. **Based on your review, what further actions, if any, do you recommend?**

No further actions are required at this time.