

0009

Outgoing
C0070004
R

From: April Abate
To: dware@foundationcoal.com
Date: 7/1/2009 7:50 AM
Subject: Castlegate Mine First Quarter 2009 Water Quality Report
Attachments: 0008.pdf; April Abate.vcf

Dennis,

Attached is your first quarter water quality report. Not much to report since none of the streams were flowing. I tried to call you about Willow Creek the other day on your office phone. Hopefully, you got my message?

Regards,
April

April A. Abate
Environmental Scientist II
Division of Oil, Gas and Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84114-5801
T: 801.538.5214
F: 801.359.3940
M: 801.232.1339

WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

June 24, 2009

TO: Internal File

THRU: James D. Smith, Permit Supervisor *JS 06/25/09*

FROM: April A. Abate, Environmental Scientist II *AAA 6-25-09*

RE: 2009 First Quarter Water Monitoring, Castle Gate Holding Company, Castle Gate Mine, C/007/0004-WQ09-1, Task ID #3225

The Castle Gate Mine is inactive, mostly reclaimed, and is awaiting appropriate conditions to apply for Phase II Bond Release.

Pertinent water monitoring requirement information is in the MRP in Sections 7.5-1 and 7.5-3, and table 7-16.

1. Was data submitted for all of the MRP required sites? YES NO

Springs –

The Permittee is not required to monitor any springs at the Castle Gate Mine.

Streams –

The Permittee is required to sample four intermittent/ephemeral streams (B-11, B-12, B-28, B-45) for flow, and the laboratory parameters outlined in Table 7-16 each quarter.

The Permittee monitored all streams as required during this quarter on March 31, 2009; none were flowing.

Wells–

The Permittee is not required to monitor any wells at the Castle Gate Mine.

UPDES–

There are no active UPDES sites at the Castle Gate Mine.

2. Were all required parameters reported for each site? YES NO

There was no flow at any of the four stream sites.

3. Were any irregularities found in the data?

YES

NO

There was no flow at any of the four stream sites.

4. On what date does the MRP require a five-year re-sampling of baseline water data.

The MRP does not require a five-year re-sampling of baseline water data.

5. Based on your review, what further actions, if any, do you recommend?

No further actions are required at this time.