

12-28-87

0002

File

SU
007/005 #5



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: December 9, 1987
8:30 AM - 10:30 AM

Permittee and/or Operators Name: Utah Fuel Company
Business Address: P.O. Box 719, Helper Utah, 84527
Mine Name: Skyline Permit Number: ACT/007/005
Type of Mining Activity: Underground XX Surface Other
County: Carbon
Company Official (s): Keith Zobell
State Official(s): James Leatherwood
Partial: XX Complete: Date of Last Inspection: November 18, 1987
Weather Conditions: Cool and Snowing
Acreage: Permitted 4834 Disturbed 75.9Regraded Seeded Bonded 75.9
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | <u>YES</u> | <u>NO</u> | <u>N/A</u> | <u>COMMENTS</u> |
|--|------------|-----------|------------|-----------------|
| 1. PERMITS | () | () | () | () |
| 2. SIGNS AND MARKERS | (X) | () | () | (X) |
| 3. TOPSOIL | (X) | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | (X) | () | () | (X) |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | () | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | () | () | () | () |
| f. EFFLUENT LIMITATIONS | (X) | () | () | (X) |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | (X) | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | () |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | () | () | () | () |

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION December 9, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers.

The perimeter markers near the topsoil stockpile located at the North Fork of Eccles Creek were inspected. The perimeter marker adjacent to the half-round diversion at the uppermost part of the fork must be relocated to the other side of the half round when weather and soil conditions permit (ie. spring thaw).

4. Hydrologic Balance:

b. Diversions.

The undisturbed diversion which collects the runoff from the upper north aspect near the truck loadout pad required minor maintenance. The culvert opening was partially obstructed with rocks. The culvert was functional at the time of inspection. There was no signs of any water passage in the diversion.

f. Effluent Limitations.


A water sample was taken from the surface facilities sediment pond at the time of inspection. The water analysis consisted of Suspended Solids and Total Dissolved Solids. The lab data was reported as follows:

| | |
|------------------------|---------|
| Suspended Solids | 52 mg/l |
| Total Dissolved Solids | 632 |

Copy of this Report:

Mailed to: John Kathman - OSM; K. Zobell - Utah Fuel

Given to: R. Harden, J. Helfrich - DOGM

Inspectors Signature and Number:  #16 Date: 12/23/87