



*File*

007/005-

### INSPECTION REPORT

INSPECTION DATE & TIME: April 09, 1988  
10:00 am to 2:00 pm

Permittee and/or Operators Name: Utah Fuel Company  
Business Address: P. O. Box 719 Helper, Utah 84527  
Mine Name: Skyline Mine Permit Number: ACT/007/005  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon  
Company Official (s): Bill Shriver  
State Official(s): David Darby  
Partial:  X Complete:  Date of Last Inspection: March 22, 1988  
Weather Conditions: Clear and windy  
Acreage: Permitted 4.834 Disturbed 75.9 Regraded  Seeded  Bonded 75.9  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION April 09, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

The Division has recently conducted a 5-year technical deficiency review of Skyline's Mining and Reclamation Plan (MRP). Deficiency comments are in the process of being edited for submittal to the operator.

4b. Diversions

Skyline was still diverting runoff around the 18" culvert normally used to carry disturbed area drainage from the upper mine pad to the sediment pond (see March 22, inspection comments). There continues to be no adverse impacts from utilizing this temporary structure. Bill Shriver indicated that the diversion restored to normal when ambient temperatures thaw the culvert.

Copy of this Report:

Mailed to: Keith Zobell-Utah Fuel, John Kathmann-OSM

Given to: Joe Helfrich and Sue Linner-DOGM

Inspectors Signature and Number:

David W. Darby #18 Date: May 2, 1988