

7-29 89
7115

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

SCU
gch

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 07/11/89
12:35 PM - 3:30 PM

Permittee and/or Operators Name: Utah Fuel Company
Business Address: P.O. Box 719, Helper, UT 84527
Mine Name: Skyline Mine Permit Number: ACT/007/005
Type of Mining Activity: Underground XX Surface Other _____
County: Carbon
Company Official (s): Keith Zobell, office; Bill Shriver, field
State Official(s): James Leatherwood
Partial: XX Complete: _____ Date of Last Inspection: 06/05/89
Weather Conditions: sunny and hot
Acreage: Permitted 4834 Disturbed 75.9 Regraded _____ Seeded _____ Bonded 75.9
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	(X)
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION 07/11/89

(Comments are Numbered to Correspond with Topics Listed Above)

11. Contemporaneous Reclamation

The seeded and mulched disturbed areas associated with the construction of the South Fork Breakout and the Forest Service Access Road were inspected. The small areas within the seeded and mulched disturbed areas have been moderately to severely impacted by grazing sheep. The area was stable, however the success of the newly germinated seedlings is of question in certain areas where it seems that the sheep were concentrated. The seeded and mulched areas should be evaluated this fall establish the success of the contemporaneous reclamation.


18. Support Facilities

The operator was in the process of constructing the fence at the South Fork Breakout, to be installed approximately four feet within the portal, that will exclude animal and man from entering the portals. Mr. Shriver indicated that placement of permit markers and topsoil identification signs will also be completed by the end of this month.

Copy of this Report:

Mailed to: Keith Zobell - Skyline Mine; Brian Smith - OSM; PFO

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number:  #16 Date: 07/18/87