



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John *027*

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

0013

INSPECTION DATE & TIME: October 25, 1991
12:30 pm to 4:00 pm

Permittee and/or Operators Name: COASTAL STATES ENERGY COMPANY
Business Address: P.O. BOX 719 HELPER, UTAH 84527 1(801)637-7925
Mine Name: WOODS CANYON EXPLORATION PROJECT - BLM PERMIT Permit Number: ACT/007/005-91A
Type of Mining Activity: Underground Surface Other
County: CARBON
Company Official(s): MARK BUNNELL
State Official(s): RANDY HARDEN, RICK SUMMERS
Partial: Complete: Date of Last Inspection: N/A
Weather Conditions: COLD, CLOUDY, SCATTERED SNOW FLURRIES, 2-4" SNOW ON GROUND
Acreage: Permitted Disturbed Regraded Seeded Bonded
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
<u>1. PERMITS</u>	<u>(X)</u>	<u>()</u>	<u>()</u>	<u>(X)</u>
<u>2. SIGNS AND MARKERS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>3. TOPSOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>4. HYDROLOGIC BALANCE:</u>				
<u>a. STREAM CHANNEL DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>b. DIVERSIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>c. SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>d. OTHER SEDIMENT CONTROL MEASURES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>e. SURFACE AND GROUNDWATER MONITORING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>f. EFFLUENT LIMITATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>5. EXPLOSIVES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>7. COAL PROCESSING WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>8. NONCOAL WASTE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>9. PROTECTION OF FISH, WILDLIFE AND</u> <u>RELATED ENVIRONMENTAL VALUES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>10. SLIDES AND OTHER DAMAGE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>11. CONTEMPORANEOUS RECLAMATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>12. BACKFILLING AND GRADING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>13. REVEGETATION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>14. SUBSIDENCE CONTROL</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>15. CESSATION OF OPERATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>16. ROADS</u>				
<u>a. CONSTRUCTION</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>b. DRAINAGE CONTROLS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>c. SURFACING</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>d. MAINTENANCE</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>17. OTHER TRANSPORTATION FACILITIES</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>
<u>18. SUPPORT FACILITIES</u> <u>UTILITY INSTALLATIONS</u>	<u>()</u>	<u>()</u>	<u>()</u>	<u>()</u>

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005-91A DATE OF INSPECTION: October 25, 1991
(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

On August 29, 1991 the BLM issued to Coastal States Energy Company, approval for conducting a three-hole coal exploration drilling program under coal exploration license application UTU-68087.

Because the proposed drilling was on BLM lease areas and was not within the existing permit area for the Skyline Mine, BLM maintained the lead for permitting the exploration activity.

Three hole were proposed in the exploration plan. Only two of the holes were actually drilled (Hole 91-26-1 and Hole 91-36-1). The third drill site (Hole 91-35-2) was accessible only by helicopter and Coastal felt that sufficient information could be derived from the other two holes.

Hole 91-26-1 was completed on or before October 7, 1991. The borehole was completed as a monitoring well at the top of the Lower O'conner coal seam and the Starpoint sandstone. Hole 91-36-1 was completed on October 22, 1991. This borehole was also completed as a monitoring well.

Reclamation of Hole 91-26-1 has been completed. the site has been regraded, mulched and seeded. Deadfall has been littered over the area to promote tree regrowth. The area disturbed has been fenced and posted as a reclamation area.


Hole 91-36-1 had just been completed the day before the inspection and reclamation activities at that location had not commenced. Due to the onset of winter conditions, the operator was not sure if reclamation of the drill pad and the access road to the site could be accomplished this year.


Photos taken of the sites the day of the inspection have been sent to file.

Copy of this Report:

Mailed to: Bernie Freeman-OSM, Keith Zobell - Utah Fuel

Given to: Daron Haddock - DOGM, Joe Helfrich - DOGM

Inspectors Signature & Number:  # 13 Date: November 7, 1991



WOODS CANYON EXPLORATION AREA

91-26-1

91-35-2

91-35-1

Proposed Access
Road Construction

Attachment 3
Proposed Drill Site and Access Road Locations
Scale: 1:24000

SKYLINE FEDERAL LEASEHOLD

Proposed Drill Site and Access Road Locations