



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

0019

March 16, 1992

Mr. Glen Zumwalt, Manager
Utah Fuel Company
P. O. Box 719
Helper, Utah 84526


Dear Mr.  Zumwalt:

Re: Division Orders 92A and 92B, Utah Fuel Company, Skyline Mine, ACT/007/005,
Folder #3, Carbon County, Utah

The Division conducted a routine inspection of the Skyline Mine on February 26, 1992. During the course of that inspection, it was determined that your Mining and Reclamation Plan does not adequately address two areas at the mine. Division Orders have been enclosed which require Utah Fuel Company to submit an application for permit change to correct these problems.

Please review the Division Orders, noting the requirements, and submit the required permit changes by the specified due date. If you have questions regarding these Orders, please contact myself, Daron Haddock, or Priscilla Burton.

Best regards,


Dianne R. Nielson
Director

Enclosures

cc: D. Haddock
L. Braxton
P. Burton
DIVIORDE.SKY

**STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING**

PERMITTEE

**Mr. Glen Zumwalt
Manager
Utah Fuel Company
P. O. Box 719
Helper, Utah 84526**

**Skyline Mine
Carbon County, Utah**

**Permit Number ACT/007/005
Division Order # 92A**

**DIVISION ORDER AND FINDINGS
of
PERMIT DEFICIENCY**

PURSUANT to R645-303-212, the DIVISION hereby ORDERS the PERMITTEE, Utah Fuel Company to make the permit changes enumerated in the FINDINGS OF PERMIT DEFICIENCY in order to be in compliance with the State Coal Program. These Findings of Permit Deficiency are to be remedied in accordance with the requirements of R645-303-220.


FINDINGS OF PERMIT DEFICIENCY

Based on a review of Utah Fuel Company's MRP and a site inspection on February 26, 1992, there has been an oversight in the plan for controlling discharge of water from ASCA Area 10; the conveyor bench. Utah Fuel Company will be required to correct the permit defects relative to ASCA #10 and demonstrate compliance with R645-301-526.220; R645-301-526.221; R645-301-526.222; R645-301-742.110; R645-301-742.120; R645-301-734; and R645-301-744.

ORDER

It is hereby ORDERED that Utah Fuel Company make the requisite permit changes in accordance with R645-303-220 and submit a complete application for permit change, addressing the FINDINGS OF PERMIT DEFICIENCY by no later than April 16, 1992.

So ORDERED, this 16th day of March, 1992, by the Division of Oil, Gas and Mining.



Dianne R. Nielson, Director
Division of Oil, Gas and Mining

**STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING**

PERMITTEE

**Mr. Glen Zumwalt
Manager
Utah Fuel Company
P. O. Box 719
Helper, Utah 84526**

**Skyline Mine
Carbon County, Utah**

**Permit Number ACT/007/005
Division Order # 92B**

**DIVISION ORDER AND FINDINGS
of
PERMIT DEFICIENCY**

PURSUANT to R645-303-212, the DIVISION hereby ORDERS the PERMITTEE, Utah Fuel Company to make the permit changes enumerated in the FINDINGS OF PERMIT DEFICIENCY in order to be in compliance with the State Coal Program. These Findings of Permit Deficiency are to be remedied in accordance with the requirements of R645-303-220.

FINDINGS OF PERMIT DEFICIENCY

Based on a review of Utah Fuel Company's MRP and a site inspection on February 26, 1992, there is a need for permit revision due to an inability to maintain ditch #DD2 (see Map 3.2.1.1) to design specifications. The slope above DD2 continually sloughs into the disturbed diversion ditch DD2. This slope is the same unstable location where previous failures eradicated the undisturbed diversion ditch DU1. Utah Fuel Company will

Page 2.

**ORDERS AND FINDINGS
ACT/007/005**


be required to correct permit defects relative to ditch #DD2 to demonstrate compliance with R645-301-732.300 and R645-301-752.200.

Utah Fuel Company will be required to correct permit defects relative to the slope above #DD2 (designated ARA-1 on Map 3.2.1.1) to demonstrate compliance with R645-301-534.150 and R645-301-331.

ORDER

It is hereby ORDERED that Utah Fuel Company make the requisite permit changes in accordance with R645-303-220 and submit a complete application for permit change, addressing the FINDINGS OF PERMIT DEFICIENCY by no later than April 16, 1992.

So ORDERED, this 16th day of March, 1992, by the Division of Oil, Gas and Mining.



Dianne R. Nielson, Director
Division of Oil, Gas and Mining