

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: March 31, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

Coal was pushed beyond the disturbed and permit area at the lower coal storage area. The quantity visible which was not covered by snow was less than 3-5 gallon buckets. A Notice of Violation was written for conducting mining activity outside of the permit area. The operator had employees clean-up the coal as the inspection continued; it was abated the same day.

4a. Diversions -

The diversion ditches generally are in good condition; this mine has an environmental maintenance program. As temperatures raise and the ground is revealed due to the melting snow, inspections must be performed more frequently.

8. Noncoal Waste -

In several snow storage areas, there is a mixture of snow and non-coal waste material. As the snow melts and the material becomes more accessible the removal should be immediate.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Coastal States Energy/Utah Fuel, Keith Zobell
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: April 6, 1993

Inspector's Signature and Number: Stephen J. Demczak 39
Stephen J. Demczak