

0025

~~Internal~~ ok
C/0051/005 - Proc 01-1b
Outgoing photos

From: Ken Wyatt
To: "CHansen@archcoal.com".MAIL.MNET
Date: 7/10/01 12:03PM
Subject: RE: PROCESSING ERRORS: Skyline Mine 1st Quarter 2001 Water Data

Hi Chris,

Thank you for getting the correct lab numbers to me. I edited the existing ones today and have processed the remaining samples for Skyline Mine 1st quarter 2001.

CS-6 was already in the database so I changed the lab number for that one. The others were still in the pipeline so I changed those and processed the samples. This clears the Skyline Mine Pipeline. These samples were edited to correct the lab numbers as per your email.

CS-6 IML 0102296-02A 2/27/2001
CS-12 IML 0102296-03A 2/27/2001
CS-13 IML 0102296-04A 2/27/2001
CS-14 IML 0102296-05A 2/27/2001
VC-6 IML 0102296-06A 2/27/2001
VC-10 IML 102296-08A 2/27/2001
VC-9 IML 0102296-07A 2/27/2001

If you have any questions, please call me.

Sincerely,
Ken Wyatt
nrogm.kwyatt@state.ut.us
(801) 538-5266

>>> "Hansen, Chris" <CHansen@archcoal.com> 07/09/01 11:54AM >>>
Ken:

I have the data sheets with the proper lab numbers. Following are the correct numbers:

CS-6 IML 0102296-02A 2/27/2001
CS-12 IML 0102296-03A 2/27/2001
CS-13 IML 0102296-04A 2/27/2001
CS-14 IML 0102296-05A 2/27/2001
VC-6 IML 0102296-06A 2/27/2001
VC-10 IML 102296-08A 2/27/2001
VC-9 IML 0102296-07A 2/27/2001

Hope these work a little better. Let me know. Thanks
Chris

[Hansen, Chris] -----Original Message-----
From: Ken Wyatt [mailto:nrogm.kwyatt@state.ut.us]
Sent: Tuesday, July 03, 2001 3:38 PM
To: Hansen, Chris; Pam Grubaugh-Littig
Cc: Steve Demczak
Subject: PROCESSING ERRORS: Skyline Mine 1st Quarter 2001 Water Data

Hello again,

Today I processed most of samples in the pipeline for the Skyline Mine. These were 1st quarter 2001 samples. The following samples would not process due to duplicate Lab Codes from IML lab. These lab codes should be unique.

The following samples are still being retained in the pipeline. If we can get the correct lab codes we can edit these to make them unique at which time they should process flawlessly.

CS-6 IML 0102296-1 2/27/2001 (This one processed since it was first)

These samples did not process due to duplicate lab Code numbers.

CS-12 IML 0102296-1 2/27/2001 (Duplicate lab Code)

CS-13 IML 0102296-1 2/27/2001 (Duplicate lab Code)

CS-14 IML 0102296-1 2/27/2001 (Duplicate lab Code)

VC-6 IML 0102296-1 2/27/2001 (Duplicate lab Code)

VC-10 IML 102296-1 2/27/2001 (Duplicate lab Code)

VC-9 IML 0102296-1 2/27/2001(Duplicate lab Code)

Chris, if you have can send me the correct lab codes I can do the edits and get these samples processed. If you have any questions please contact me.

Sincerely,
Ken Wyatt
(801) 538-5266
nrogm.kwyatt@state.ut.us <mailto:nrogm.kwyatt@state.ut.us>

>>> "Hansen, Chris" <CHansen@archcoal.com> 06/28/01 04:21PM >>>
Pam:

I have uploaded to the EDI the first quarter 2001 water monitoring results for SUFCO, Skyline, Soldier Canyon, and Dugout Canyon Mines. Several sites at each mine location, with the exception of SUFCO, were inaccessible due to snow cover. All accessible sites were monitored. If you have any questions about the electronic data, please give me a call.

Chris Hansen