

TECHNICAL MEMORANDUM

Utah Coal Regulatory Program

September 10, 2004

TO: Internal File

FROM: Wayne H. Western, Team Lead *WHW*

RE: North Lease Subsidence Mining, Canyon Fuel Company LLC, Skyline Mine, C007/0005, Task ID #1976

SUMMARY:

The following analysis is a review of information received by the Division On July 1, 2004, the Division received the North Lease Subsidence Mining amendment. The information provided consists primarily of reports and studies that were outlined to be conducted when the North Lease was originally permitted in November 2002. Reports includes a GPS stream-channel profile survey of Winter Quarters Canyon and Woods Canyon in central Utah, and a report titled, "Riparian Plant Community Survey Near Scofield, Utah". Both reports are submitted as additional baseline information to study the potential effects of subsidence in the North Lease area – primarily in the perennial reaches of Winter Quarters Canyon and Woods Canyon.

TECHNICAL MEMO

TECHNICAL ANALYSIS:

OPERATION PLAN

MINING OPERATIONS AND FACILITIES

Regulatory Reference: 30 CFR 784.2, 784.11; R645-301-231, -301-526, -301-528.

Analysis:

CFC intended that the North Lease subsidence permit modification submittal to address all the regulations needed for them to get approval to conduct longwall mining in the North Lease area. The information in the amendment does not adequately update the MRP. CFC did not update specific parts of the MRP such as Section 2.5.2, where they state that longwall mining is not allowed in under Winter Quarters Canyon. In addition, Drawing 4.17.1-1, Extent of Planned and Controlled Subsidence Areas, does not even show the addition of the North Lease area.

The Division will not list all sections of the MRP that must be updated if CFC plans on conduction full extraction mining in the North Lease area. CFC has the responsibility of updating the entire MRP to include longwall mining in the North Lease area.

Findings:

The information in the application is not considered adequate to meet them minimum requirements of the regulations. Before approval, CFC must provide the following in accordance with:

R645-301-121.200, CFC must update all sections of the MRP that pertain to mining the North Lease. The updates must include all maps and drawing as well as text.

EXISTING STRUCTURES:

Regulatory Reference: 30 CFR 784.12; R645-301-526.

Analysis:

"Existing Structure" means a structure or facility used in connection with or to facilitate coal mining and reclamation operations for which construction began prior to January 21, 1981.

There are no existing structures within the North Lease Area.

Findings:

The information in the amendment is adequate to meet the minimum requirements of this section of the regulations.

RELOCATION OR USE OF PUBLIC ROADS

Regulatory Reference: 30 CFR 784.18; R645-301-521, -301-526.

Analysis:

CFC will not relocate or use any additional public roads in connection with the North Lease. There is an old trail in the bottom of Winter Quarters Canyon. That structure should not be affected by subsidence.

Findings:

The information in the application is considered adequate to meet them minimum requirements of the regulations.

COAL RECOVERY

Regulatory Reference: 30 CFR 817.59; R645-301-522.

Analysis:

CFC did not update the economic coal recovery plan to include extraction from the North Lease. CFC must include a detailed economic coal recovery plan in the amendment or other information that the Division can use to make a finding.

The Division often relies on information in the resource recovery protection plan R2P2. The Division usually finds that the R2P2 contains enough information to make a determination about economic coal recovery.

TECHNICAL MEMO

Findings:

The information in the application is not considered adequate to meet them minimum requirements of the regulations. Before approval, CFC must provide the following in accordance with:

R645-301-522, The plan for maximum economic coal recovery must be updated to include information on the North Lease.

SUBSIDENCE CONTROL PLAN

Regulatory Reference: 30 CFR 784.20, 817.121, 817.122; R645-301-521, -301-525, -301-724.

Analysis:

Renewable Resources Survey

CFC conducted renewable resource surveys of the North Lease area. CFC found that renewable resources such as perennial streams, Woods Canyon Creek and Winter Quarters Creek, are within the permit boundaries. Those subsidence surveys are part of Section 4.17.1 of the MRP.

Subsidence Control Plan

CFC submitted modifications subsidence control plan to cover changes because of the addition of the North Lease.

The subsidence control plan must contain the following information:

- A description of the method of coal removal, such as longwall mining, including the size, sequence, and timing for the development of underground workings. CFC did not state those requirements in the amendment. Map 3.3-2, Lower O'Conner "A"/Flat Canyon Five Year Projected Mine Plan, show longwall panels in the North Lease. However, in Section 4.17.1 of the MRP, CFC states that only development mining will occur in the North Lease. CFC does not mention switching from development mining to longwall mining in the amendment.
- In a phone conversation between Wayne Western of the Division and Chris Hansen of CFC on August 24, 2004, Chris mentioned that CFC submitted the amendment as part of the process to get permission to use longwall mining methods in the North Lease area.

TECHNICAL MEMO

- CFC must clarify their intentions but stating in the amendment that CFC seeks approval to conduct longwall mining in the North Lease area. This deficiency was stated in Mining Operations and Facilities section of the technical analysis.
- A map of underground workings which describes the location and extent of areas in which planned-subsidence mining methods will be used and which includes all areas where measures will be taken to prevent or minimize subsidence and subsidence related damage and where appropriate, to correct subsidence-related material damage.
- Map 4.17.3-1A, North Lease Presubsidence Survey Map, shows the areas where subsidence is anticipated, the amount of subsidence (potential subsidence contours) and those areas where CFC believes that subsidence cracks could occur. All of the areas where CFC shows the potential for surface subsidence cracks to occur are on ridges, not in valleys. In a personal conversation between Wayne Western of the Division and Dale Harber of the USFS, Mr. Harber stated that the USFS is concerned that mining under perennial streams, especially perennial streams with less than 600 feet of cover could be damaged by subsidence cracks.
- Drawing 4.17.1-1, Extent of Planned and Subsidence Areas is out of date and does not show the North Lease area. The map must be updated.
- A description of the physical conditions, such as depth of cover, seam thickness, and lithology, which affect the likelihood or extent of subsidence and subsidence-related damage. The depth of cover, coal isopachs, is shown Map 2.2.7-2, Lower O'Conner "A"/Flat Canyon Overburden Map. The depth of cover ranges from 500 feet to 2,000 feet. The seam thickness is shown on Map 2.2.7-1, Lower O'Conner "A"/Flat Canyon Isopach. The geology report is in Volume A-3 of the MRP.
- A description of monitoring, if any, needed to determine the commencement and degree of subsidence so that, when appropriate, other measures can be taken to prevent, reduce, or correct material damage. CFC did not change the monitoring program, which consists of a commitment to conduct annual aerial surveys. In addition CFC committed specially to conduct infrared aerial photography each year on the North Lease area.
- The Division now requires permittees to commit to conduct on the ground reconnaissance at least six months after a panel has been mined out but no more than twelve months afterwards.
- Except for those areas where planned subsidence is projected to be used, a detailed description of the subsidence control measures that will be taken to prevent or minimize subsidence and subsidence-related damage, including, but not limited to: backstowing or

TECHNICAL MEMO

backfilling of voids; leaving support pillars of coal; leaving areas in which no coal is removed, including a description of the overlying area to be protected by leaving the coal in place; and, taking measures on the surface to prevent material damage or lessening of the value or reasonably foreseeable use of the surface. CFC proposes to use longwall mining methods for all areas of the North Lease. All mined area with the exception of mains are scheduled to be subsided.

- A description of the anticipated effects of planned subsidence, if any. In Section 4.17.1 of the MRP, CFC specifically mentions the anticipated subsidence effects in the North Lease area. CFC does not anticipate any subsidence related impacts on the pack trail in the bottom of Winter Quarter Canyon. CFC states that no subsidence will occur in the area until permission is granted by the USFS and the Division.
- CFC must submit a detailed description of the anticipated effects of subsidence for the North Lease area. The study must contain site-specific references such as analysis of annual subsidence reports for mines in the area and other historical information.
- A description of the measures to be taken to mitigate or remedy any subsidence-related material damage to, or diminution in value or reasonably foreseeable use of the land, or structures or facilities to the extent required under State law. In Section 4.17.4, Mitigation of Subsidence Effects, of the MRP, CFC states “that mitigation will be contingent of upon the findings of the subsidence monitoring program. Surface subsidence experienced to date, as shown in the 1987 and 1988 annual reports, has been less than 50% of the mining height even after 2 years have passed. As data are collected, methods of mitigation will be formulated.”
- CFC must update the subsidence mitigation plan because they have sixteen years of additional data.
- CFC stated that impacted water rights if any, will be replaced as discussed in Section 2.5.2 of the MRP. In that section CFC states “The current 2002 mine plans do not anticipate longwall mining in the Winter Quarters area thus allowing the mine time to obtain the needed baseline data.
- Additional information on how CFC will mitigate loss of state appropriated water rights is in Section 2.5.3, Alternative Water Supply, of the MRP. In that section, CFC mentions that mitigation methods include sealing cracks in streambeds and providing water from other sources. CFC did not list specific methods on how they would seal cracks.
- CFC must list specific methods for sealing cracks in streambeds and site references for the effectiveness each method.

- Other information specified by the Division as necessary to demonstrate that the operation will be conducted in accordance with the performance standards for subsidence control.

Performance Standards For Subsidence Control

Notification

Findings:

The information in the application is not considered adequate to meet them minimum requirements of the regulations. Before approval, CFC must provide the following in accordance with:

R645-301-525.420, Drawing 4.17.1-1, Extent of Planned and Subsidence Areas must show the extent of possible subsidence in the North Lease area.

R645-301-525.440 and R645-525.490, CFC must incorporate a plan to the surface area over each panel walked no earlier that six months after mining ceases but no more than twelve months after mining ceases to inspect for surface subsidence features or develop an alternative plan that will detect surface subsidence features.

R645-301-525.460, CFC must submit a detailed description of the anticipated effects of subsidence for the North Lease area. The study must contain site-specific references such as analysis of annual subsidence reports for mines in the area and other historical information. CFC must specifically state what effects subsidence is expected to have on the perennial streams in the North Lease area.

R645-301-525.440, CFC must update the subsidence monitoring program by incorporating the data that they collected since 1988. In Section 4.17.4 of the MRP, CFC committed to update the monitoring program as more data became available.

R645-301-525.480, CFC must include a description of the methods that could be used to repair perennial stream channels. The description will include references stating the results of such methods in similar conditions.

SLIDES AND OTHER DAMAGE

TECHNICAL MEMO

Analysis:

The addition of the North Lease will not effect this section.

Findings:

The information in the application is considered adequate to meet them minimum requirements of the regulations.

RECOMMENDATIONS:

The Division should deny the application until all of the above mentioned deficiencies are adequately addressed.