



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Gregg Galecki Environmental Coordinator
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Thursday, October 12, 2006
Start Date/Time:	10/12/2006 10:00:00 AM
End Date/Time:	10/12/2006 3:00:00 PM
Last Inspection:	Friday, September 15, 2006

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cold 50's

InspectionID Report Number: 1110

Accepted by: pgrubaug *JK*

10/26/2006

Permittee: **CANYON FUEL COMPANY LLC**
 Operator: **CANYON FUEL COMPANY LLC**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,374.00	Total Permitted
79.12	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
 State
 County
 Fee
 Other

Types of Operations

- Underground
 Surface
 Loadout
 Processing
 Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee is meeting the following Permit Conditions:

- 1) Submit Water Monitoring data in electronic format to the Division.
- 2) Canyon Fuel Co. must submit all existing studies and data for the update of the PHC as a result of the mine inflows.
- 3) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek.
- 4) Canyon Fuel Co. must have a qualified person compile and analyze past macroinvertebrate studies on Eccles Creek into one report.
- 5) Canyon Fuel Co. must initiate an update to and further evaluation of the Hydrologic and Channel-Stability Evaluation of Eccles and Mud Creek.

Permit Renewal was April 30, 2002, and expires on April 30, 2007. The state permit for full extraction in North Lease was approved by the state on December 2, 2005 and mining plan approval by the Secretary of the Interior was approved on February 24, 2006.

The permittee has the following permitting action with the Division: Midterm Permit Review.

Inspector's Signature: *Steve Demczak*

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Friday, October 20, 2006

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted an amendment to extend the refuse pile for the Skyline Mine. I had several conversations with the permittee about the construction of the pile. I have informed the permittee that MSHA may need to review the new designs of the refuse pile. The refuse pile must meet CFR 77.214 and CFR 77.215 requirements. It would be prudent for the permittee to receive a letter stating that the new designs meet these requirements. This would facilitate the permitting process. The Division cannot make a favorable finding until the refuse pile meets the requirements of 30 CFR 77.214 and 30 CFR 77.215. This implies that a MSHA approval would be needed.

3. Topsoil

The topsoil piles at the refuse and mine site were inspected with no signs of water or wind erosion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

All sediment ponds were inspected and contained water. No hazardous conditions were noticed during the inspection.

4.d Hydrologic Balance: Water Monitoring

The permittee is in the process of entering the water monitoring information into the EDS. The permittee is in continual contact with the Division on the entering of the information.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was near-filled to capacity. The permittee has projected that abnormal amount to refuse will be mined this winter. The permittee is trying to find temporary storage areas until the extension pile extension amendment receives Division approval.

18. Support Facilities, Utility Installations

No additional facilities have been constructed since the last inspection.