

ok



State of Utah
Department of
Natural Resources

MICHAEL R. STYLER
Executive Director

Division of
Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Gregg Galecki Environmental Coordinator
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070005
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, November 08, 2006
Start Date/Time:	11/8/2006 10:00:00 AM
End Date/Time:	11/8/2006 1:00:00 PM
Last Inspection:	Thursday, October 12, 2006

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 1127

Accepted by: pgrubaug
 11/28/2006

Permittee: **CANYON FUEL COMPANY LLC**
 Operator: **CANYON FUEL COMPANY LLC**
 Site: **SKYLINE MINE**
 Address: **HC 35 BOX 380, HELPER UT 84526**
 County: **CARBON**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

10,374.00	Total Permitted
79.12	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The permittee is meeting the following Permit Conditions:

- 1) Submit Water Monitoring data in electronic format to the Division.
- 2) Canyon Fuel Co. must submit all existing studies and data for the update of the PHC as a result of the mine inflows.
- 3) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek.
- 4) Canyon Fuel Co. must have a qualified person compile and analyze past macroinvertebrate studies on Eccles Creek into one report.
- 5) Canyon Fuel Co. must initiate an update to and further evaluation of the Hydrologic and Channel-Stability Evaluation of Eccles and Mud Creek.

Permit Renewal was April 30, 2002, and expires on April 30, 2007. The state permit for full extraction in North Lease was approved by the state on December 2, 2005 and mining plan approval by the Secretary of the Interior was approved on February 24, 2006.

The permittee has the following permitting action with the Division: Midterm Permit Review.

Inspector's Signature:

Steve Demczak
 Steve Demczak, Environmental Scientist III

Date Thursday, November 09, 2006

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The permittee has three permitting actions with the Division. These are 2006 Permit Renewal, New Sediment Pond at the Waste Rock Site, and Modification of Table of Contents.

3. Topsoil

The topsoil pile at the mine site is heavily vegetated. The permittee was seeding the topsoil piles at the waste rock site during the inspection.

4.a Hydrologic Balance: Diversions

The permittee will need to clean out several diversions throughout the property. Sediment from recent rain storms have deposited sediment within the diversions.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected with no hazardous conditions noticed during the inspection. The permittee inspected the ponds for the third quarter of 2006.

UPDES permit will expire on 11/30/09.

4.d Hydrologic Balance: Water Monitoring

The permittee was in the process of taking fourth quarter water samples.

7. Coal Mine Waste, Refuse Piles, Impoundments

The waste rock site was inspected and I found no hazardous conditions. The permittee was reclaiming the slopes of the refuse pile and spreading out seed during the inspection. The permittee performed the fourth quarter refuse pile inspection on 11/26/06. No hazardous conditions were reported. This document was P.E. certified.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

12. Backfilling And Grading

The permittee was in the process of placing topsoil on to the outslope of the refuse pile. There is only one topsoil pile left at the refuse area.

13. Revegetation

The permittee was seeding the slopes of the waste rock site during the inspection.

18. Support Facilities, Utility Installations

No new support facilities were constructed since the last inspection.

Permit Number: C0070005
Inspection Type: COMPLETE
Inspection Date: Wednesday, November 08, 2006

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

The permittee is insured by ACE American Insurance Co. The policy will expire on 7/31/07.