

a

Incoming
C0070005
#3544
OK

OGMCOAL - Task 3544 Supplemental

From: "Galecki, Gregg" <GGalecki@archcoal.com>
To: "ogmcoal@utah.gov" <ogmcoal@utah.gov>
Date: 5/12/2010 12:27 PM
Subject: Task 3544 Supplemental
CC: "daronhaddock@utah.gov" <daronhaddock@utah.gov>, "angelanance@utah.gov" ...
Attachments: Task3544_Supplement_5-12-10.pdf

All:
After speaking with Mr. Peter Hess, he identified one (1) minor text omission on page 3-69 of Task ID 3544.

It was discussed with Ms. Angela Nance that the attached page could be added to the said submittal.

Gregg A. Galecki
Environmental Engineer
Canyon Fuel Company, LLC
Skyline Mine
(435)448-2636

***Email Disclaimer: The information contained in this e-mail, and in any accompanying documents, may constitute confidential and/or legally privileged information. The information is intended only for use by the designated recipient. If you are not the intended recipient (or responsible for delivery of the message to the intended recipient), you are hereby notified that any dissemination, distribution, copying, or other use of, or taking of any action in reliance on this e-mail is strictly prohibited. If you have received this e-mail communication in error, please notify the sender immediately and delete the message from your system.

seeded and mulched, and, where needed, additional straw bales and/or silt fences, erosion mats installed to treat any runoff. Part of the area also has a collection ditch below the straw bales. Where needed, this ditch has a series of straw bales across the drainage at 15-20 feet intervals. Much of the ditch has become well grassed-in and is almost indistinguishable from the adjacent undisturbed areas and does not need any additional silt control devices as the runoff has already been treated with strawbales and/or silt fences.

Area 16. This area is south of the truck dump and is shown on Map No. 3.2.1-3. This area contains .61 acres and is the fill slope of the access road. The slope has been reseeded and basically has a well established cover of vegetation. The disturbance around the overland conveyor towers have been seeded and mulched, and have additional straw bales and/or silt fences, erosion mats, where needed, to treat any surface runoff. (See Area 10a)

Area 17. This area is south of the RLO sediment pond and is shown on Map No. 3.2.1-3. This area contains .35 acres and has been classified as an "Alternative Sediment Control Area." Much of the area has been paved. There are straw bales and/or silt fences and three small straw dikes to treat any runoff water. One of these straw dikes is on the UDOT rights-of-way of SR-96. This treatment location has been approved by UDOT (refer to UDOT letter dated 7/18/89 from L. Archie Hamilton, District Four Pre/construction Engineer, Page 3-70).

Area 17a. This area is adjacent to RRLO sediment ponds and is shown on Map 3.2.1-3. This area contains .15 acres and has been classified as an "Exempt Area" since it is the outslope of the sediment pond embankment.

Areas 18. This area is adjacent to the Railroad Loadout structure and is shown on Map No. 3.2.1-3. This area contains .1 acres and has been classified as an exempt area as the entire area is paved.

Area 19. This area is adjacent to the Railroad loadout structure and is shown on Map No. 3.2.1-3. This area contains .1 acres and has been classified as an Small Area Exemption (SAE) as the entire area is paved "~~Alternate Sediment Control Area~~". ~~This area has been covered with approximately 4 inches of clean 2-inch rock material. The runoff is also treated with strawbales and/or silt fence.~~

seeded and mulched, and, where needed, additional straw bales and/or silt fences, erosion mats installed to treat any runoff. Part of the area also has a collection ditch below the straw bales. Where needed, this ditch has a series of straw bales across the drainage at 15-20 feet intervals. Much of the ditch has become well grassed-in and is almost indistinguishable from the adjacent undisturbed areas and does not need any additional silt control devices as the runoff has already been treated with strawbales and/or silt fences.

Area 16. This area is south of the truck dump and is shown on Map No. 3.2.1-3. This area contains .61 acres and is the fill slope of the access road. The slope has been reseeded and basically has a well established cover of vegetation. The disturbance around the overland conveyor towers have been seeded and mulched, and have additional straw bales and/or silt fences, erosion mats, where needed, to treat any surface runoff. (See Area 10a)

Area 17. This area is south of the RLO sediment pond and is shown on Map No. 3.2.1-3. This area contains .35 acres and has been classified as an "Alternative Sediment Control Area." Much of the area has been paved. There are straw bales and/or silt fences and three small straw dikes to treat any runoff water. One of these straw dikes is on the UDOT rights-of-way of SR-96. This treatment location has been approved by UDOT (refer to UDOT letter dated 7/18/89 from L. Archie Hamilton, District Four Pre/construction Engineer, Page 3-70).

Area 17a. This area is adjacent to RRLO sediment ponds and is shown on Map 3.2.1-3. This area contains .15 acres and has been classified as an "Exempt Area" since it is the outslope of the sediment pond embankment.

Areas 18. This area is adjacent to the Railroad Loadout structure and is shown on Map No. 3.2.1-3. This area contains .1 acres and has been classified as an exempt area as the entire area is paved.

Area 19. This area is adjacent to the Railroad loadout structure and is shown on Map No. 3.2.1-3. This area contains .1 acres and has been classified as a Small Area Exception (SAE) as the entire area is paved.