



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

July 29, 2014

Wes Sorenson, Mine Manager
Canyon Fuel Company, LLC
HC 35 Box 380
Helper, Utah 84526

Subject: Water Tank Replacement, Canyon Fuel Company, LLC, Skyline Mine,
C/007/0005, Task ID #4640

Dear Mr. Sorenson:

The Division has reviewed your application at the Skyline Mine. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Attachment
O:\007005.SKY\WG4640\Deficiencies.docm



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

PID: C0070005
TaskID: 4640
Mine Name: SKYLINE MINE
Title: WATER TANK PIPE REPLACEMENT

Environmental Resource Information

Permit Area

Deficiencies Details:

R645-301-121.200, The listing of ""Permit Area to be Reclaimed"" as stated on page 1-37 is now 122.57 acres. This listing was incorrectly totaled and should be 122.31 acres. The narrative at the top of page 1-37 should also be changed to read the same figure, 122.31 acres.

pburton