

0049

PLATEAU MINING COMPANY

A Subsidiary of Getty Mineral Resources Company

P. O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

* File ACT/007/006

Copy to Wayne
& Lee for
action & response
none needed
JIM
done
Dart

AUG 10 1981

July 31, 1981

Mr. James W. Smith, Jr.
Coordinator of Mined Land Development
Division of Oil, Gas, and Mining
1588 West North Temple
Salt Lake City, UT 84116

Re: Mud Water Lease Extension Approval
Federal Coal Lease #U-37045
Star Point Mine
ACT/007/006
Carbon County, UT

Dear Mr. Smith:

In response to your letter of July 17, 1981, to Mr. Floyd Tucker, we are submitting the enclosed map entitled "Star Point No. 2 Mine Plan - Federal Lease U37045 Five-Year Development - - 3rd Seam." The maps indicate the position of the faces as of July 23, 1981, and the projected advance through January 1, 1985. Also, shown on the map, are the locations of our subsidence monitoring monuments within the lease.

You will notice that some of the monuments lie below the coal seam. This is not, however, an area for concern since these monuments are for photogrammetry control only, and horizontal or vertical movement of any area in between these monuments can be detected by photogrammetric techniques.

We appreciate your rapid solution of our problem in this lease, and if we can be of any further assistance in this matter, do not hesitate to contact us.

Sincerely,

PLATEAU MINING COMPANY

John F. Rosner
Staff Engineer

AUG 9 1981

DIVISION OF
OIL, GAS & MINING

JFR/gd
enc.

cc: Don Crane, OSM, Denver
Reed Christensen, USFS, Price
Jackson Moffitt, USGS, SLC
Floyd Tucker, PMC
Steve Rigby, PMC
Mike Dmitrich, PMC