

0053

**PLATEAU MINING COMPANY**

A Subsidiary of Getty Mineral Resources Company

P. O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

File Act 10071006

Copy to Jim, Jean

RECEIVED  
JUL 0  
DIVISION OF  
OIL, GAS & MINING

June 26, 1981

Tom Portle  
Division of Oil, Gas and Mining  
1588 West North Temple  
Salt Lake City, UTAH 84116

RE: MEETING AND INSPECTION 06/25/81 - 11:00 a.m.

Dear Tom,

I appreciated your input on our proposed method of top soil removal and redistribution in reference to the Refuse Pile.

I will send you a rough draft of our proposal for you to look at prior to our formal submittal for approval. I have been in contact with our consultants and will have supporting documentation as to the depth of soil and the necessary buffer zone. As this information is available I will see you receive copies.

In reference to the inspection; the four areas of concern are:


1. Top soil pile drainage adjacent to Sedimentation Pond #5.
2. Boundry delineation adjacent to Pond #5.
3. Berm area around diesel tank adjacent to #1 Portal.
4. Rip Rap in drainage area adjacent to conveyor line.

I have addressed each area of concern and will advise you as they are implemented.

I enjoyed meeting both you and Jean and appreciate the air of cooperation you displayed.

Sincerely,

PLATEAU MINING COMPANY

  
Mel Coonrod  
Environmental Coordinator

cc: F. Tucker  
S. Rigby