

0030

PLATEAU MINING COMPANY

A Subsidiary of Getty Mineral Resources Company

P. O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

file ACT/007/806

May 15, 1981

Ms. Sandy Pruitt
Division of Oil, Gas and Mining
1588 West North Temple
Salt Lake City, UT 84116

RECEIVED

MAY 20 1981

Certified Letter No. 204761

**DIVISION OF
OIL, GAS & MINING**

Re: Areas of Concern Letter Dated April 21, 1981

Dear Ms. Pruitt,

I would like to advise you concerning actions taken in regards to items 6 and 8 in your letter of April 21, 1981.

No 6. Perimeter markers were installed today on the property lines in the vicinity of the major disturbance areas. Due to the complexity of property lines on the remainder of our property and lease lines, it will be impossible to install perimeter markers on the entire permit area by May 17, as called for in your letter. Where roads cross property or lease lines markers will be installed. Markers will be installed on major section and quarter section corners.

No 8. Plans to raise the level of the slurry pond have been abandoned. The slurry will be cleaned out and placed on the refuse pile. The slurry will be treated the same as the refuse ie spread and compacted after drying.

If you have questions please call.

Sincerely,

PLATEAU MINING COMPANY



Ben Grimes,
Engineering and Reclamation Specialist

BG/gd

cc: Steve Rigby
Joe Ronan
Alden Pierce
Floyd J. Tucker