

**PLATEAU MINING COMPANY**

A Subsidiary of Getty Mineral Resources Company

P. O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

File  
ACT/007/006

April 24, 1981

Ms. Sandy Pruitt  
Division of Oil, Gas and Mining  
1588 West North Temple  
Salt Lake City, UTAH 84116

RECEIVED

APR 28 1981

DIVISION OF  
OIL, GAS & MINING

RE: NOV N 81-2-3-3

Dear Ms. Pruitt:

In confirmation of our April 24th conversation and the conversation I had with Tom Portle on April 23rd, I would like to advise regarding our abatement actions taken in response to the recent violations issued by your office.

I will address each violation and relate to you what has been done to rectify the problems.

NOV #1 - We will put together a permit application addressing the applicable regulations.

I received today word from Bonnerville Engineering Company that the State Department of Health has given verbal approval on a building permit for the Drain Field and the associated transmission line from the New Bathhouse Office complex, written approval [Building Permit] will be picked up by Bonnerville Engineering Company on Monday, April 27th.

NOV #2 - The topsoil from the leach field and material storage area was removed and segregated starting at approximately 11:30 a.m. on April 16th and was completed by 8:00 a.m. on April 17th.

Immediately upon completion of the leach field, the topsoil will be re-distributed and the area will be reclaimed.

NOV N 81-2-3-3  
April 24, 1981  
Page 2

NOV #3 - A diversion ditch was constructed along the edge of the canyon to the North of the leach field. This was in agreement with your recommendation on the day of the service of the NOV's. This ditch was completed by 8:00 a.m. April 17th.

Thank you for your advise and consideration in these regards.

Sincerely,

PLATEAU MINING COMPANY



Ben Grimes  
Engineering & Reclamation Specialist

BG/jhs

cc: Floyd Tucker - P.M.C.  
Steve Rigby - P.M.C.  
Joe Ronan - Getty  
Alden Pierce - Getty