

October 7, 1981

Inspection Memo  
to Coal File:

RE: Scofield Area Coal  
Exploration  
Bishopgate Coal Corp.  
CEP/007/006  
Carbon County, Utah

On September 21, 1981, Inspector Sandy Pruitt visited an exploration site subject to NOV group #81-2-11-3, as the follow up inspection to determine the reclamation and compliance status at these newly permitted sites.

The site located on the Winter Quarter's Cayon access road (drill hole #81-5-2) has been recontoured with only the sumps remaining until all of the drilling fluid evaporates. Immediately adjacent to this drill hole, site preparation for drill hole #81-5-1B was underway. A pad and sumps had been constructed on a previous drill site #81-5-1 which had been recontoured on August 13, 1981.

Drilling was underway at drill hole #81-8-1 located south of Scofield along a pre-existing cattle road. The drilling pad is situated directly adjacent to an ephemeral drainage but disturbed area runoff is adequately contained. Drill hole #81-8-2 had recently been abandoned. No reclamation of the site had been performed and the drill hole had not been plugged. Drill site #81-8-3 which is also adjacent to an ephemeral drainage had been grubbed. All drill sites inspected were in compliance or being prepared for compliance with UMC 815. All drill sites were permitted and no violations were warranted.

  
SANDY PRUITT  
RECLAMATION OFFICER

cc: Tom Ehmett, OSM  
Scott Williams, Bishopgate

SP/btm