


0001



Sanders Exploration, Limited

THE ENERGY CENTER • 1901 PROSPECTOR SQUARE • POST OFFICE BOX 1329 • PARK CITY, UTAH 84060 • (801) 649-8212



October 31, 1983

DIVISION OF
OIL, GAS & MINING

Mr. Dave Lof, Field Specialist
4241 State Office Building
Salt Lake City, Utah 84114

Re: Recontouring and Seeding of Drill Hole
81-5-1P

Dear Mr. Lof:

Please be informed of the successful attempts to reclaim
Drill Hole 81-5-1P.

The hole was cemented and recontoured during mid August
1983. The hole was prepared for seeding and then seeded during
mid October. Since you were able to view the site I hope it
appeared satisfactory.

Could you please terminate the violation NOV N82-4-13-1.

Thank you for your help.

Sincerely,

SANDERS EXPLORATION, LIMITED

Billy H. Green, Vice President

BHG/p

FILE ~~1007/006~~ CEP/007/006



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES

CHARLES R. HENDERSON
Chairman

CLEON B. FEIGHT
Director

DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Vacation or Termination of Notice or Order

To the Following Permittee or Operator:

Name BISHOPSGATE COAL CORP.
Mailing Address P.O. Box 3357 PARK CITY, UT 84060
State Permit No. CEP/007/006

Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):

Notice of Violation No. N 82-4-13-1 Y TV dated Oct. 22, 19 82.

Cessation Order No. C _____ Y TV dated _____, 19 _____.

Violation No. 1 is hereby X Terminated EFFECTIVE 10/12/83 Vacated because:

Violation No. _____ is hereby _____ Terminated _____ Vacated because:

Violation No. _____ is hereby _____ Terminated _____ Vacated because:

Date of Service Nov. 1, 1983 David Lof
Signature of Authorized Representative

Time of Service or Mailing 9:30 X a.m. _____ p.m. DAVID LOF #4
Name and I.D. No.

SHORTLY AFTER ISSUING THE VIOLATION WINTER WEATHER CONDITIONS SET IN SO THAT THE OPERATOR COULD NOT RECLAIM THE SITE DURING THE FALL OF 1982. IN THE SPRING OF 1983 ROAD CONDITIONS AND SITE CONDITIONS WERE SUCH THAT RECLAMATION HAD TO BE FURTHER DELAYED UNTIL THIS FALL.

ON OCT. 12, 1983 I CONDUCTED AN ON SITE INSPECTION AT WHICH TIME I FOUND THE OPERATOR ON SITE SEEDING & MULCHING THE RECONTOURED SITE.