

PLATEAU MINING COMPANY

A Subsidiary of Getty Mining Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

December 1, 1983

CC

ACT/007/006
FOLDER #3

Mr. David Lof
Division of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, UT 84114

Subject: Concerns Expressed From
Inspection of November 8-9

**DIVISION OF
OIL, GAS & MINING**

Dear Dave:

This letter is in response to your phone call to myself on November 17 regarding your inspection on November 8 & 9.

Pond 4

We have decided to install two piezometers to attempt to monitor the water seeping from the bank below the pond. One piezometer will be placed in the pond embankment and the other somewhere in the bank below the pond where the seepage is. The exact location of the second piezometer depends on where we can auger down a hole. The bank is very steep and will dictate the location.

Shortly after your inspection, we started receiving snow and adverse weather. It may not be possible to install the piezometers until next spring, but we will try as soon as we locate an auger.

Channel Crossing Below Pond 4

The road in this location is a Class III road with minimal use; therefore, we would request permission to install a stream ford. The channel is an intermittent stream which further simplifies the matter.

We would propose placing D50-8 inch rock in the crossing and cementing it in place to prevent loss by the higher flows. The width of the rock crossing will depend on the design flow of the channel and must be shallow enough to allow vehicular crossing.

We will attempt to place the rock now and hope to finish it; otherwise, we may have to wait until spring to complete the job.

Ditch 14 Discharge Structure

A design for this structure is being sent to you under separate cover from Vaughn Hansen Associates.

If you have questions, please call.

Respectfully,

Ben Grimes
Environmental Coordinator

PLATEAU MINING COMPANY

A Subsidiary of Getty Mining Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

December 1, 1983

RECEIVED
DEC 1 1983

Mr. David Lof
Division of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, UT 84114

Subject: Concerns Expressed From
Inspection of November 8-9

DIVISION OF
OIL, GAS & MINING

Dear Dave:

This letter is in response to your phone call to myself on November 17 regarding your inspection on November 8 & 9.

Pond 4

We have decided to install two piezometers to attempt to monitor the water seeping from the bank below the pond. One piezometer will be placed in the pond embankment and the other somewhere in the bank below the pond where the seepage is. The exact location of the second piezometer depends on where we can auger down a hole. The bank is very steep and will dictate the location.

Shortly after your inspection, we started receiving snow and adverse weather. It may not be possible to install the piezometers until next spring, but we will try as soon as we locate an auger.

Channel Crossing Below Pond 4

The road in this location is a Class III road with minimal use; therefore, we would request permission to install a stream ford. The channel is an intermittent stream which further simplifies the matter.

We would propose placing D50-8 inch rock in the crossing and cementing it in place to prevent loss by the higher flows. The width of the rock crossing will depend on the design flow of the channel and must be shallow enough to allow vehicular crossing.


We will attempt to place the rock now and hope to finish it; otherwise, we may have to wait until spring to complete the job.

Ditch 14 Discharge Structure

A design for this structure is being sent to you under separate cover from Vaughn Hansen Associates.


If you have questions, please call.

Respectfully,



Ben Grimes
Environmental Coordinator

BG:mo



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

October 17, 1983

Mr. Ben A. Grimes
Environmental Coordinator
Plateau Mining Company
P.O. Drawer PMC
Price, Utah 84501

RE: Minor Revision to Approved
Corner Canyon Fan Project
Star Point Mines
ACT/007/006
Folder #4
Carbon County, Utah

Dear Ben,

The Division has received your October 11th, 1983, letter regarding the minor revision to the approved Corner Canyon Fan Project. The revision involves the burying of the diesel fuel storage tank on the breakout pad instead of the above ground storage as previously proposed.

This letter constitutes the Division's approval for said change irrespective of any other necessary approvals.

Thank you for notifying us and keeping our staff updated with current operations. If we can be of any further assistance, please call.

Sincerely,

JAMES W. SMITH, JR.
COORDINATOR OF MINED
LAND DEVELOPMENT

JWS/jvb

cc: D. Wayne Hedberg
David Lof
Tom Portle
Allen Klein, OSM