

0054

# PLATEAU MINING COMPANY

RECEIVED

A Subsidiary of Getty Oil Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

JUN 18 1984

DIVISION OF OIL  
GAS & MINING

June 15, 1984

Mr. David Lof  
Division of Oil, Gas, and Mining  
4241 State Office Building  
Salt Lake City, Utah 84114

RE: NOV 84-4-1-1

Dear Dave:

The plan, as submitted, to construct a permanent berm, inlet box and culvert had to be modified. During the time the temporary berm was in place, numerous vehicles were damaged because of the abrupt angle the berm was on in relation to the traffic pattern.

To solve the problem, was put the permanent berm on more of an angle to ease the impact on vehicles. In doing this, it eliminated the need for the inlet box and culvert; the attached plan shows the modification. Runoff will flow along the berm and in a lined ditch to the existing inlet box, accomplishing the goal.

The berm and ditch were completed on June 12. If you have any questions, please call.

Respectfully,

PLATEAU MINING COMPANY

Ben Grimes  
Environmental Coordinator

BG/kc

Attachment

CC: WAYNE


DWEL.

FOLDER #3

FILE ORIGINAL IN ACT/007/006

FOLDER #7


DETAIL A



RECEIVED

JUN 18 1984

DIVISION OF OIL  
GAS & MINING



NOV 84-4-1-1

PERMANENT ABATEMENT  
PLAN

PLATEAU MINING CO