

0059

PLATEAU MINING COMPANY

A Subsidiary of Getty Oil Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

FILE ACT/007/006
FOLDER #7

RECEIVED

MAY 29 1984

DIVISION OF OIL
GAS & MINING

May 24, 1984

Mr. David Lof
Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

RE: NOV 84-4-7-6 No. 1 of 6

Dear David:

As you are aware, we installed a 14-inch diameter culvert in Ditch No. 16 to eliminate plugging the ditch; refer to the attached memo.

The drainage area contributing to the culvert is 6.2 acres; this is 41 percent of the entire drainage area for Ditch No. 16.

Total Ditch 16 flow - $0.62 \text{ cfs} \times 41\% = 0.25 \text{ cfs}$.

The culvert is on a 10 percent slope and will carry approximately 9 cfs; therefore, the culvert is adequate. It was oversized to facilitate cleaning.

If you need further information, please call.

Respectfully,

PLATEAU MINING COMPANY

Ben Grimes /sd

Ben Grimes
Environmental Coordinator

BG:sd

Enclosure

