

0030

PLATEAU MINING COMPANY

File: 407/007/006
3

A Subsidiary of Getty Oil Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

RECEIVED

June 6, 1985

JUN 10 1985

DIVISION OF OIL
GAS & MINING

Mr. Rick Summers
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RE: PHONE CALL, May 28, 1985, DITCHES 6 AND 12

Dear Rick:

I have re-evaluated our request of October 25, 1983, and find that what I called ditch 12 is actually now called Ditch 7E. The condition of this ditch is the same as stated in the October 25, 1983 letter; it is stable though somewhat deep. Reconstructing it would mean disturbing a lot of well established vegetation, and would disturb existing topsoil.

Ditch 6 is in the same condition as it was in 1983; there is very little erosion. We are planning to reclaim this ditch this construction season, during reclamation efforts at the No. 1 Mine. We would, therefore, reaffirm our original request.

If you need additional information, don't hesitate to call.

Respectfully,



Ben A. Grimes
Environmental Coordinator

lc