

0053



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

ACT/007/006#2

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

July 6, 1987

Mr. Ben Grimes  
Senior Environmental Engineer  
Plateau Mining Company  
P. O. Drawer PMC  
Price, Utah 84501

*Ben*  
Dear Mr. Grimes:

Re: Updated Mine Sequence Maps, Plateau Mining Company, Star Point  
Mines, ACT/007/006, Folder #2, Carbon County, Utah

During the meeting with the Division and Plateau Mining Company on June 24, 1987, regarding the Incidental Boundary Change, it was disclosed by Plateau that the present mine sequence map for the Wattis Seam (Map 6) is not correct as planned. Mining is planned in the southwest portion of Section 7, T15S, R8E during the next 5 years, as explained by Mr. Bob Lauman.

Mining will not be approved in that section for the five-year renewal as the present five-year renewal maps do not reflect this. Water (springs) and subsidence monitoring programs are dependent on the mine sequence. Therefore, it is imperative that accurate mine sequence maps with the most accurate workings projected be contained in the approved MRP.

This letter is to advise Plateau that updated mine sequence maps must be in the approved MRP to avoid enforcement action in the future.

If you have any questions, please call me.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Lowell'.

Lowell P. Braxton  
Administrator  
Mineral Resource Development  
and Reclamation Program

PGL/djh  
cc: J. Whitehead  
P. Grubaugh-Littig  
8808R/10