

NO. N87-9-3-1

notice of violation

To the following Permittee or Operator:

Name The Team Mining Company  
 Mine Star Point  Surface  Underground  Other  
 County Carbon State Utah Telephone 801/637-2875  
 Mailing Address P.O. Drawer PMC Pite, Ut 84501  
 State Permit No. ACT/007/006  
 Ownership Category  State  Federal  Fee  Mixed  
 Date of inspection April 2, 19 87  
 Time of inspection 4:00  a.m.  p.m. to 5:00  a.m.  p.m.  
 Operator Name (other than Permittee) same as above  
 Mailing Address same as above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing April 2, Time of service/ mailing 5:00  a.m.  p.m.

Bob Lauman  
 Permittee/Operator representative

Manager of Tech Services  
 Title

Robert S. Lauman  
 Signature

Holland Shepherd  
 Division of Oil, Gas & Mining representative

Reclamation Spec.  
 Title

H.S. Shepherd  
 Signature

#9  
 Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



**NOTICE OF VIOLATION NO. N 87-9-3-1**

Violation No. 1 of 1

Nature of violation

Failure to divert runoff through disturbed area so as not to cause additional erosion. Failure to carry on a mining activity in accordance with the approved plan.

Provisions of act, regulations or permit violated

UMC 817.45 (iii) (e)

UMC 771.19

UCA 40-10-12 (7)

Portion of operation to which notice applies

The Lion Peak parking yard culvert (center culvert) has developed a leak. The leak is located at the top of the culvert and has caused an erosion gully down the full length of the slope. The gully is approximately 1 1/2 deep.

Remedial action required (including any interim steps)

- 1) repair leaking culvert (temporarily)
- 2) fully repair culvert - as conditions warrant

Abatement time (including interim steps)

- 1) To be repaired by April 13, 1987
- 2) To be completed by May 30, 1987