

0010



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

October 12, 1989

TO: Richard V. Smith, Permit Supervisor

FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pgl*

RE: **Permit Defect-UMC 784.23(b)(3) and UMC 784.13(b)(3),  
Cyprus-Plateau Mining Company, Starpoint Mine, ACT/007/006,  
Folder #4, Carbon County, Utah**

## Synopsis and Analysis

Upon review of the disturbed or bonded areas for the Starpoint Mine, some deficiencies in the surface facilities maps were noted. The bonded areas are not found on Map 44, Sheets F-12 and G-12.

Additionally, during a review of the permit, Map 47, Post Disturbance Topography and Cross-Sections, Sheet E-13 was missing, as well as Map 71, Mine Permit Area.

## Recommendation

The applicant must add the reclamation bonded area to the legend and delineate appropriately on Map 44, Sheets F-12 and G-12.

Map 47, Sheet E-13 and Map 71 must be submitted.

djh  
AT45/96