

0038



ACT/007/006 #2
Cyprus Plateau Mining Corporation
P.O. Drawer PMC
Price, Utah 84501
(801) 637-2875

July 3, 1992

RECEIVED

JUL 06 1992

DIVISION OF
OIL GAS & MINING

Ms. Pamela Grubaugh-Littig
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Ms. Littig,

Re: Ditches 51, 57 and 58 Design Information

Enclosed, please find 3 copies of calculations on the referenced ditches. The calculations document that with the new design storm requirements (10 year, 6 hour event), ditches 57 and 58 do not require lining, ditch 51 requires lining with riprap with a size requirement of $D_{50}=1.0'$.

Eight copies of revised Maps 731.720a and 731.720c and Tables 742a and 742c are enclosed for direct insertion into our MRP document. These maps reflect the latest calculations.

Ditch 51 will be lined with the appropriate riprap by August 31.

Respectfully,

A handwritten signature in black ink, appearing to read 'Ben Grimes'.

Ben Grimes
Sr. Environmental Engineer

Enclosures

File: ENV 2-5-2-16-44
Chron: BG920611