



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 7/19/2000 / 9:30a.m.-2:30p.m.
Date of Last Inspection: 6/21/2000

SW
PHH

Mine Name: Star Point Mine County: Carbon Permit Number: ACT/007/006
Permittee and/or Operator's Name: Plateau Mining Corporation
Business Address: 847 Northwest Highway 191, Helper, Utah 84526
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Vicky Miller
State Officials(s): Steve Demczak Federal Official(s): None
Weather Conditions: Warm, 90's
Existing Acreage: Permitted- 9,060 Disturbed- 220 Regraded- Seeded- Bonded- 220
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ XXX Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 listing various permit conditions and their evaluation status.

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 7/19/2000

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee will be revising a map to show permit and disturbed area boundaries.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were inspected; minor maintenance is needed on a few. The permittee will clean these.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were inspected with no ponds discharging during the inspection. No hazardous conditions were noted during the inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences provide the sediment control on the BTCA areas. The mine has installed redundant sediment control measures including straw bales, silt fences, sumps, and check dams to retain sediment near the source.

18. SUPPORT FACILITIES -

The permittee has a contractor on site removing the belt lines and feeders.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau)

Henry Austin (OSM)

Given to: Pam Grubaugh-Littig (DOGM)

Filed to: Price Field Office

Date: July 31, 2000

Inspector's Signature: _____

Stephen J. Demczak
Stephen J. Demczak

#39