



United States
Department of
Agriculture

Forest
Service

Manti-La Sal
National Forest

Supervisor's Office
599 West Price River Drive
Price, UT 84501
Phone # (435) 637-2817
Fax # (435) 637-4940

File Code: 2820-4

Date: July 27, 2004

Mary Ann Wright
Associate Director
Utah Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, UT 84501

RECEIVED

JUL 29 2004

DIV. OF OIL, GAS & MINING

*Jeanning
C/00710006
Cory PAM*

Dear Ms. Wright:

We concur that reclamation of the Corner and Mudwater Breakouts and the Vent hole on Gentry Mountain for the Plateau Mining Company Starpoint Mine has been completed satisfactorily, consistent with Phase I bond release criteria. Additionally, water-monitoring wells on Gentry Mountain have been plugged and reclaimed, however, these sites need to be monitored until re-vegetation has been determined to be in conformance with established ground cover standards.

As previously reported to your staff, several subsidence cracks within the Starpoint Mine Permit Area on Castle Valley Ridge pose a hazard to the public and wildlife. Reclamation of these cracks must be completed before we can concur with additional phases of bond release.

If you have any questions, please contact Tom Lloyd (435-636-3596) or Carter Reed (435-636-3547).

Sincerely,

Alice B. Carlton

ALICE B. CARLTON
Forest Supervisor

cc:
D-2/3

