

0003

**KAISER
STEEL**

KAISER STEEL CORPORATION
SUNNYSIDE GOAL MINES
SUNNYSIDE, UTAH 84539
TELEPHONE 801-888-4421

RECEIVED
DEC 23 1982

22 December 1982

Mr. Barton Kale, Insp.
Div. of Oil, Gas & Mining
4241 State Office Bldg.
Salt Lake City, Utah, 84114

DIVISION OF
OIL, GAS & MINING

re: NAOC#82-6-2-2 & #82-6-3-1
Sunnyside Mines
ACT/007/007

#7

Dear Bart,

This letter is to inform you of the progress on numerous "areas of concern" at the Sunnyside Mine site:

- NAOC82-6-2-2; 1. Sediment control measures at various locations(12-17-82).
- section along fence abutting Grassy Trail Creek. dirt berm installed 12-16-82.
 - storage area berm abutting #2 Canyon drainage. area cleared & berm renewed 12-14-82.
 - small storage area north of #2 canyon drainage. constructed berm 11-29-82.
 - Water canyon storage area. oil drums removed & straw-bales placed 12-13-82.
 - Grassy Trail Creek crossing. no add'n useage to date.
2. Coarse Refuse disposal area drainage (12-24-82)
begin field survey of area.

Kaiser Steel Corp hereby requests an extention of time on item 2 of NAOC82-6-2-2 to properly outline & plan the drainage patterns and determine proper sediment control structures to be employed on the site. Please extend thru 28 Jan 1983.


NAOC82-6-3-1; Soil material placed under conveyor at #2 Cyn drainage.
placed straw-bales around soil material 12-20-82.

Please be aware that since we are in the winter season and the ground is frozen, most of the remedial work is minimal & acts just as a stop-gap measure until the weather warms up & improves, then the items will properly be improved & the problems resolved.

Also the leak in the Whitmore Canyon Mine Water Discharge Pond supply line has been repaired.

May we have your favorable consideration on the above items. It is most difficult to properly satisfy the concerns in this very cold weather.

Sincerely,


John S. Huefner, PE
Civil Engineer

cc: Denise Dragoo