

0001

Document Information Form

Mine Number: C/007/007

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: December 15, 1982

Explanation:

Inspection Memo

cc:

File in:
C/ 007 , 007 , Internal

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

December 15, 1982

Inspection Memo
to Coal File

RE: Kaiser Steel Corporaton
Sunnyside Complex #7
ACT/007/007
Carbon County, Utah

A partial inspection was conducted by Barton Kale, of the Division at the above mentioned minesite on December 8, 1982.

An inspection of the sediment pond at the base of Slaughter Canyon revealed that no maintenance work had been done since the last inspection on November 23-24, 1982. Damage to the pond had supposedly taken place in September and the pond should have been regularly monitored since that time. As a result violation 82-6-2-2 was issued and reads as follows:

Nature of Violation

Failure to maintain appropriate sediment control measures using the best technology available to prevent, to the extent possible, additional contributions of sediment to stream flow, outside the permit area.

Failure to maintain sedimentation ponds to prevent short circuiting to the extent possible.

Provisions of the Regulations Violated

UCA 40-10-18 2(c)(ii)
UMC 817.45 (i)
UMC 817.46 (i)

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0001 Date 12-15-82

In C/ 007, 007, Internal

For additional information

Portion of the Operation to Which Notice Applies

Sediment pond at the base of Slaughter Canyon.

Remedial Action Required

1. Maintenance of present sediment pond structure.
2. Submit adequate plans addressing any area which may be inadequately designed and constructed to ensure proper conveyance and treatment of disturbed area runoff. Implimentation of those plans upon approval by the Division.

Time for Abatement

1. Repair maintenance to outslope to be completed by December 23, 1982.
2. Submit adequate plans addressing any areas as named in #2 above within 60 days.

Inspection Memo
ACT/007/007
December 15, 1982
Page Two

Due to transporting problems involved in the topsoil placement at the Number II Canyon drainage, that topsoil will be allowed to stay at its present location as long as topsoil protection is intact. As a result NAOC 82-6-4-1 was issued. It reads as follows:

Nature of Concern

Inadequate topsoil redistribution in a manner that protects the topsoil from wind and water erosion before and after it is seeded and planted.

Pertinent Regulation of Permit Condition

UMC 817.24 (b)(3)

Portion of Operation to Which Notice Applies

Retopsoiled area in Number II Canyon, under conveyor.

Compliance Action Required

Maintain erosion controls on this site to protect against water erosion, regrade top edges of drainage.

Deadline

December 23, 1982

Kaiser has not started discharging out of the new manshaft pipe. They have been notified that they need to submit plans to State Health.

The two previous NAOC's have not been abated yet as of this time. Approximately two more weeks remain.

Kw for
BARTON KALE
FIELD SPECIALIST

BK/tck

cc: Tom Ehmett, OSM
John Huefner, Kaiser Steel Corporation
Joe Helfrich, DOGM

Statistics: See Tower Resources memo dated, December 10, 1982