



0047

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Dr. G. A. (Jim) Shirazi, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

June 13, 1983

Mr. Douglas C. Pearce
Kaiser Steel Corporation
Western Coal Operations
Sunnyside, Utah 84539

RE: Rail Cut Pond Review
Outcome of Field Visit
Assessment of Rail Cut
Pond Area
Sunnyside Mines
ACT/007/007, Folder No. 3
Carbon County, Utah

Dear Doug:

After visiting the Rail Cut Area it is felt that the existing 24 inch culvert is sufficient to handle the flow from the areas in question (AREA I and II), Drawing No. C4-0058. The following stipulations must be agreed to in order that approval is granted for construction of the Rail Cut Pond.

1. The inlet to the 24 inch culvert must be maintained and kept clear of debris.
2. The outlet must be riprapped and stabilized to prevent erosion.
3. Stipulations #1 and #3 found in the Division's letter of May 26 has been addressed verbally by the applicant during the field visit on June 9, 1983, but the Division would like actual calculations of riprap size.

If these stipulations are adequately met, then the Division will approve construction of the Rail Cut Pond.

Sincerely,

Thomas Munson

THOMAS MUNSON
RECLAMATION HYDROLOGIST

TM/btb

cc: S. Cox, DOGM
B. Kale, DOGM