

0072

**KAISER
COAL**

KAISER COAL CORPORATION
Sunnyside Coal Mines
P.O. Box D
Sunnyside, Utah 84539
Telephone (801) 888-4421

File: ACT/007/007
#7

RECEIVED

July 2, 1985

JUL 05 1985

Mr. Dave Lof
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

DIVISION OF OIL
GAS & MINING

RE: NOV N85-4-19-1, 1 of 1
Remedial Plans, Part B
ACT/007/007, Sunnyside Mines

Dear Mr. Lof:

Water discharged from the Clear Water Pond has met State and Federal water quality standards historically. Failure to meet standards as cited in this violation was a result of high water and slurry levels in Slurry Cell No. 1. To prevent future failures of a filtration dike, a minimum of 2 feet of free board will be maintained in each pond. Maximum water levels will be marked with a metal stake set near the filter. Water levels in the pond will be monitored and recorded during pond inspections. These precautions will ensure proper operation of the ponds.

Damage to the ponds will be repaired by: 1) removal of the remaining slurry material in the ponds, 2) removal of the filter dikes, 3) reconstruction of the filter dikes and 4) cleaning out slurry material in the discharge pipes. Slurry will be disposed of in the West Slurry Cell. Removal of the slurry is presently under way.

Sincerely yours,



Douglas C Pearce
Mine Engineer