

0049

**KAISER
COAL**

KAISER COAL CORPORATION
Sunnyside Coal Mines
P.O. Box 10
Sunnyside, Utah 84539
Telephone (801) 888-4421

Mine file
J Whitehead
W. Hedberg
ACT/007/007
RECEIVED
MAR 06 1987

DIVISION OF
OIL, GAS & MINING

March 4, 1987

Mr. Lowell P. Braxton, Administrator
Mineral Resource Development & Reclamation Program
Utah Division of Oil, Gas & Mining
355 W. North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Coarse Refuse Toe Seep
Sunnyside Mines
ACT/007/007

Dear Mr. Braxton:

Kaiser has reviewed Mr. D. Wayne Hedberg's letter of February 23, 1987, responding to Kaiser's request to terminate treatment of the Coarse Refuse Toe Seep. Kaiser is willing to agree to the conditions in Mr. Hedberg's letter (which referenced Mr. Jim Fricke's February 18, 1987 analysis) provided that sufficient latitude is granted Kaiser in the event further treatment is required. This latitude might include treatment methods other than chemical separation and physical removal of the iron.

An example of the methods referred to is the use of designed wetlands which may remove and utilize the iron. The methods would be dependent upon state-of-the-art techniques available at the time and could involve experimental measures. The method to be used would be selected by Kaiser. At such time, the quality to be achieved would be that necessary to achieve compliance with NPDES limitations then in effect.

Should you have any questions concerning this matter, please contact me.

Sincerely,



Carl W. Winters
Senior Mining Engineer

cc: B. J. Bourquin