



0001

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

file 007/007#2
Norman H. Bangert, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

December 11, 1987

TO: John Whitehead, Permit Supervisor

FROM: James R. Fricke, Reclamation Hydrologist *JRF*

RE: Review of As-Built Design, Plans for Coarse Refuse Toe Pond (CRT) and Sunnyside Surface Facilities Pond (SSF), Kaiser Coal Corporation, Sunnyside Mine, ACT/007/007, Folder #2, Carbon County, Utah

The operator has submitted a response (December 8, 1987) to the Division's request (August 13, 1987) to modify the approved plans to reflect the as-built field disposition of the ponds.

The plans are technically acceptable, however, the MRP references all maps with plate denotation. The present drawings do not have the plate numbers. The CRT map number, D4-0158, should have Plate III-5 depicted. The SSF map, drawing number D4-0159, should have Plate number III-12 depicted on all drawings. Additionally, sheet 2 of 2 for the SSF plan was not received. The operator should label all drawings for the SSF plan in consecutive order; i.e., sheet 1 of 3, 2 of 3, and 3 of 3.

The plans must be modified as stated above before submittal to the MRP is appropriate.

djh
0798R/27