


0007

**KAISER
COAL**

KAISER COAL CORPORATION
Sunnyside Coal Mines
P.O. Box 10
Sunnyside, Utah 84539
Telephone (801) 888-4421

November 17, 1988



Mr. Jim Fricke
Department of Natural Resources
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Jim:

Re: Borrow Area Sediment Pond Riprap Design
Sunnyside Mines, ACT/007,007

Folder # 2

Per our phone conversation on Monday, November 14, 1988, Kaiser Coal Corporation will wet grout the riprap in place on the inlet and outlet ditches.

The field changes moving the inlet ditch to the 8:1 slope from the side slope and the cleanout ramp toward the center of the west side will be shown on the as-built drawing. As-built information will also be included for the ditches as appropriate.

Please feel free to call if you have any questions.

Thank you for your assistance in this matter.

Sincerely,

A handwritten signature in cursive script, appearing to read "Bill".

W. P. Balaz, Jr., P. E.
Manager of Administration

WPB:th

cc: Bill Warmack