

Sunnyside Coal Company

ACT/007/007

Operations • Highway 123 • P.O. Box 99 • Sunnyside, Utah 84539

April 15, 1991

RECEIVED

APR 17 1991

DIVISION OF
OIL GAS & MINING

Lowell P. Braxton
Associate Director of Mining
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Mr. Braxton:

Re: Division Order To Sunnyside Coal Company

On March 21, 1991, Sunnyside Coal Company reviewed an order from the Division dated March 11, 1991. Sunnyside Coal Company responded to this order on April 10, 1991, by providing the Division with the appropriate changes requested.

The purpose of this letter is to clarify the deficiency shown as #1 in the Division Order:

1. R614-301-731.750 requires that there be "... cross sections for each existing and proposed sedimentation pond, impoundment and coal processing waste bank, dam or embankment. The cross-sections will be prepared and certified according to R614-301-512.100." The cross sectional maps of the Clear Water Pond and the #1 and #2 Slurry Cells don't accurately depict the said facilities. The maps and cross-sections in Sunnyside Mines PAP do not comply with R614-301-231.750. Therefore, the PERMITTEE must submit certified maps and cross-sections of the Clear Water Pond and the #1 and #2 Slurry Cells.

As already stated in Sunnyside Coal Company's letter on April 10, 1991, Plate III-13 already contained cross sections of the Clear Water Slurry Pond and Slurry Ponds #1 and #2.

Per my conversation with Division Inspector Henry Sauer, it became evident that the Division wanted Plate III-13 updated to depict the as-built condition of the filtering system utilized by the Clear Water Pond and Slurry Ponds #1 and #2 and not just the cross sections as

Corporate Offices
The Registry
1113 Spruce Street
Boulder, CO 80302
303-938-1506
FAX: 303-938-5050

Sales Office
1350 17th Street
Suite 350
Denver, CO 80202
303-534-3348
FAX: 303-825-8626

West Coast Division
1345 Astoria Drive
Fairfield, CA 94533
707-425-4506

Operations
Highway 123
P.O. Box 99
Sunnyside, UT 84539
801-888-4421
FAX: 801-888-2581

Mr. Lowell P. Braxton
Page 2
April 15, 1991

indicated in the division order. More specifically, the filter pipes from Slurry Ponds #1 and #2 are not used and have not been used since the ponds were constructed.

Sunnyside Coal Company submitted on April 10, 1991, a certified as-built copy of Plate III-13 to show the existing system of the Clear Water Pond and Slurry Ponds #1 and #2.

If you have any questions please feel free to call me.

Sincerely,

A handwritten signature in cursive script that reads "Karl R. Houskeeper".

Karl R. Houskeeper
Environmental Coordinator

KRH:dp

cc: Joe Fielder
Gary Gray