

Sunnyside
Coal Company

Operations • Highway 123 • P.O. Box 99 • Sunnyside, Utah 84539

RECEIVED

DEC 18 1992

DIVISION OF
OIL GAS & MINING

December 15, 1992

Mr. Henry Sauer
 Senior Reclamation Soils Specialist
 Division of Oil, Gas & Mining
 355 West North Temple
 3 Triad Center, Suite 350
 Salt Lake City, Utah 84180-1203

Dear Henry:

Re: NOV92-32-14-1, Failure To Treat The Coarse Refuse Seep

Sunnyside Coal Company's efforts to treat the Coarse Refuse Seep in order to abate the above NOV have been hampered by the cold weather. We have insulated the 55-gallon barrel of flocculent, but the drip supply line to the seep refuses to flow; i.e., frozen.

We are actively pursuing a flocculent in the form of a jelly log. We know flocs of this type were used in 1983 by Kaiser Steel, but the product is no longer manufactured. We are looking for other vendors.

For this reason, Sunnyside Coal Company requests an extension of two weeks until December 29, 1992, to abate the above NOV.

Your understanding and approval are appreciated.

Sincerely,



Pete Hess
 Environmental Coordinator

PH:cj

Corporate Offices
 The Registry
 1113 Spruce Street
 Boulder, CO 80302
 303-938-1506
 FAX: 303-938-5050

Sales Office
 1350 17th Street
 Suite 350
 Denver, CO 80202
 303-534-3348
 FAX: 303-825-8626

West Coast Division
 1345 Astoria Drive
 Fairfield, CA 94533
 707-425-4506

Operations
 Highway 123
 P.O. Box 99
 Sunnyside, UT 84539
 801-888-4421
 FAX: 801-888-2581