

0015



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: Exploration:
Inspection Date & Time: 4/27/94 9:00 am - 2:00 pm
Date of Last Inspection: 3/22-24/94 & 3/30/94

Mine Name: Sunnyside Coal Mine County: Carbon Permit Number: ACT/007/007
Permittee and/or Operator's Name: Sunnyside Coal Company (SCC)
Business Address: PO Box 99, Sunnyside, Utah 84539
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Henry Sauer, Peter Hess & Scott Milovich
Company Official(s): Darrel Leonard Federal Official(s): None
Weather Conditions: Cold and Snowing, Approximately 5 inches snow on the ground
Existing Acreage: Permitted-14475 Disturbed-310 Regraded-0 Seeded-0 Bonded-310
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June)_____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION: April 27, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

On April 25, 1994, the undersigned inspector attempted to contact, by phone, Sunnyside Coal Company's (SCC) resident agent Mr. Bob Burnham. Mr. Burnham's secretary informed me that he was not available. I requested that she leave a message. She agreed to do so and I told her to tell Mr. Burnham that I would be conducting a partial state inspection of the mine site. The inspection would commence at approximately 8:30 a.m., Wednesday, April 27, 1994. At the beginning of the inspection, Mr. Peter Hess, a former SCC employee, suggested that I contact Darrel Leonard, Mine Superintendent. Mr. Leonard informed me that he was not previously aware of the planned partial state inspection. I informed Mr. Leonard that the main objective of the inspection would be to ascertain the extent of the disturbance on site and compare it with the disturbed area boundary in the mining and reclamation plan. This objective was not sufficiently completed because of the snow cover and poor visibility.

4. HYDROLOGIC BALANCE: b. SEDIMENT PONDS AND IMPOUNDMENTS

The Hoist House Sedimentation Pond was observed. The 18-inch diameter riser pipe on the primary spillway had been replaced with a 24-inch riser pipe. Two inactive inlet culverts had been backfilled with soil. The inlet culvert which is supposed to remain active had been inadvertently covered with soil. Mr. Leonard was instructed to uncover the inlet culvert and construct outlet protection as specified in Amendment # ACT/007/007-93CC. I informed Mr. Leonard that an as-built survey of the pond would need to be accomplished and submitted to the Division for approval. The as-built is a provision of the violation abatement requirements. In addition to the requirements of the violation, the permittee must adequately describe the disposition, classification and location of the material excavated during the enlargement of the Hoist House Sedimentation Pond.

d. WATER MONITORING


The discharge from UPDES outfall #001 was observed. No visible indications of longwall oil or other oil contamination were noted.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Bob Burnham (SCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: _____



#32

Date: 5/11/94