

September 28, 1983

Inspection Memo to
Coal File

RE: Blazon Coal Company
CEP/007/009
Carbon County, Utah

Sandy Pruitt inspected Blazon Drill Sites B1 and B2 on August 31, 1983 to determine the adequacy of the abatement measures for NOV # N82-2-8-2. Both drill sites were adequately recontoured, the drill holes had been covered so it could not be determined with certainty if the holes had been properly plugged. The sites had already been seeded but germination success is likely to be poor due to drouth and frost heaving. While the equipment was available, Sanders Exploration Co. also reclaimed an unpermitted drill site located just north of site B2. NOV # N82-2-8-2 was terminated as a result of this inspection.


SANDY PRUITT
FIELD SPECIALIST

SP/jvb

cc: Tom Ehmett, OSM
Joe Helfrich, DOGM
Allen Smith, North American Equities

STATISTICS:

See Wellington Prep Plant memo dated September 23, 1983