

0010

File ACT 1007/011 #2

cc: L. Kunzler

D. Haddock

UNITED STATES FUEL COMPANY

P.O. Box A
Hiawatha, Utah 84527

(801) 637-2252
TELEX: 453-123

June 23, 1989

RECEIVED
JUN 26 1989

DIVISION OF
OIL, GAS & MINING

Ms. Susan Linner, Permit Supervisor
Division of Oil, Gas and Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Re: Mid-Permit Term Review, Hiawatha Mines
Complex, ACT/007/011

Dear Ms. Linner:

In response to items 3 and 4 of your letter dated May 19, 1989, please find the following information enclosed.

1. Letter to EPA and Utah Department of Health addressing the overflow discharge from the South Fork water tank.
2. Results of rip rap size analysis performed for the Middle Fork, South Fork and upper railroad yard diversions.

Sincerely,

Robert Eccli

Robert Eccli
Sr. Mining Engineer

RE:lj

Enclosure:

